



SERVICE BULLETIN

Date issued: 10-16-96

Number: 96-10-2

Synopsis: Affects users of Van's full swivel tailwheel. A steel steering arm (VA-154S) replaces the aluminum arm (VA-154) originally supplied. The aluminum arms were wearing faster than anticipated. Units shipped after 10-10-96 contain the steel arm.

Correction: The VA-154S steel steering arm is simply substituted for the VA-154 aluminum steering arm. The new arm will be supplied free of charge upon request.